THINGS TO KNOW 333 HIGHLAND AVENUE, WINCHESTER

ROOF	MAIN ROOF (ASPHALT) WAS A COUPLE YEARS OLD WHEN SELLERS MOVED IN (JULY 2011). THE OTHER ROOF WAS ADDED IN 2012.
HEATING SYSTEM	OIL BURNER & TANK WERE A COUPLE YEARS OLD WHEN SELLERS MOVED IN (JULY 2011).
HOT WATER TANK	ELECTRIC STONE LINED TANK IS ~30 YEARS OLD. SHOULD LAST ~50 YEARS.
WINDOWS	 DOUBLE HUNG & STORM WINDOWS ON ORIGINAL HOUSE: AGE UNKNOWN 3RD FLOOR STORM WINDOWS IN ATTIC REAR SECTION OF HOUSE (REMODELED) HAS PELLA INSULATED DOUBLE PANE WINDOWS
ANNUAL HEATING COSTS	SEPT. TO MAY - \$2,600
NUMBER OF HEATING & COOLING ZONES	2 HEATING ZONES & 2 COOLING ZONES ZONE 1: FLOOR 1; ZONE 2: FLOORS 2, 3
TOWN UTILITIES	TOWN OF WINCHESTER
CLOSING DATE	AS SOON AS POSSIBLE
SCHOOL DISTRICTS	LINCOLN ELEMENTARY SCHOOL MCCALL MIDDLE SCHOOL WINCHESTER HIGH SCHOOL



*Information on this document is to the best of the seller's knowledge. This is not a legal representation and buyer should perform should perform their own due diligence.

ADDITIONAL INFORMATION

333 HIGHLAND AVENUE, WINCHESTER

UPDATES DURING OWNERSHIP

- BLEW IN INSULATION IN ALL SIDES & FLOORS OF HOUSE, INCLUDING GARAGE
- RESIDED ENTIRE HOUSE & GARAGE
- NEW WINDOWS
- ADDED RECESSED LIGHTING IN BEDROOMS & COMMON AREAS
- ADDED WAINSCOTING IN COMMON AREAS & MASTER BEDROOM
- PAINTED ENTIRE INSIDE OF HOUSE
- RENOVATED OLDER MOULDINGS & PLASTER TO REFRESH PROPERTY
- ADDED BRAND NEW WALPOLE WOODWORKERS FENCE ALONG DRIVEWAY, SIDE YARD & BESIDE GARAGE WITH ARBOR ON SIDE YARD ENTRANCE
- BRAND NEW FRONT DOOR WITH SCREEN DOOR & SIDE LIGHTS INSTALLED TO IMPROVE WINTER HEATING & SUMMER COOLING REQUIREMENTS



*Information on this document is to the best of the seller's knowledge. This is not a legal representation and buyer should perform should perform their own due diligence.